## III. REMARKS

Claims 1, 20 and 24 have been amended to more particularly point out that the method includes forming the gap or void to remove a rail defect, but the gap or void does not include the base of the rail and at least a portion of the web remains intact. Antecedency has been corrected in claim 20. Typo; traphical and editing errors have also been corrected in claim 24.

October 5, 2006

Respectfully submitted,

David C. Brezina

Barnes & Thornburg LLP P.O. Box 2786 Chicago, IL 60690

Phone: 312-214-4802 Facsimile: 312-759-5646

Attorney for Applicant Registration No.: 34,128